



Biddeford Fire Department
Incident Report

Page: 1
08/17/2021

Incident #: 20-4280-IN Exp. 0

Call #: 20-39454

Location: 10 CLIFFORD ST
10 CLIFFORD ST
BIDDEFORD, ME 04005

Census Tract: 179-
District: Biddeford 09
Station: BIDDEFORD CENTRAL

Officer In Charge: WHEELER, ERIC on 10/27/2020
Report By: WHEELER, ERIC on 10/27/2020
Approved By: WHEELER, ERIC on 10/27/2020

Basic Incident Information

Incident Type: False alarm or false call, other - BFD RESIDENTIAL
ALARM MALFUNCTION

Property Use: Multifamily dwelling
Actions Taken: Action taken, other

Owner: 10 CLIFFORD ST
10 CLIFFORD ST
BIDDEFORD, ME 04005

Resources Used Summary

Alarm: 10/27/2020 @ 0707 Arrived: 10/27/2020 @ 0711
Cleared: 10/27/2020 @ 0725

Shift: C Alarms: 0 Aid: None

	<u>Apparatus</u>		<u>Personnel</u>
Suppression:	1	Suppression:	3
EMS:	0	EMS:	0
Other:	1	Other:	1

Casualties Summary

	<u>Deaths</u>		<u>Injuries</u>
Fire Service:	0	Fire Service:	0
Civilian:	0	Civilian:	0

People and Entities Involved Type Sex Age Home # Work

1

**Biddeford Fire Department
Incident Report**

**Page: 2
08/17/2021**

Incident #: 20-4280-IN Exp. 0

#	Apparatus	Type	Dates/Times	Per Use	Actions Taken
1	Biddeford A/C Dexter BIDC2	Chief officer car	Disp 10/27/2020 @ 0710 Arr 10/27/2020 @ 0711 Clr 10/27/2020 @ 0725 InQt 10/27/2020 @ 0725 InSv 10/27/2020 @ 0725	1 Other	- Investigate
2	Biddeford Engine 26 BIDE26	Engine	Disp 10/27/2020 @ 0709 Arr 10/27/2020 @ 0712 Clr 10/27/2020 @ 0721 InQt 10/27/2020 @ 0721 InSv 10/27/2020 @ 0721	3 Suppr	- Action taken, oth

#	ID	Personnel	Start	End	Dty	Station	App
1	10326	Froman, Paul	10/27/2020 @ 0709	10/27/2020 @ 0721	ST	CEN	BIDE26
2	44675	Maloney, Todd	10/27/2020 @ 0709	10/27/2020 @ 0721	DR	CEN	BIDE26
3	38700	Labrecque, Paul	10/27/2020 @ 0707	10/27/2020 @ 0725	DC	CEN	BIDC2
4	68625	WHEELER, ERIC	10/27/2020 @ 0709	10/27/2020 @ 0721	OI	CEN	BIDE26

Incident #: 20-4280-IN Exp. 0

NARRATIVE FOR CAPTAIN ERIC WHEELER

Ref: 20-4280-IN

Entered: 10/27/2020 @ 0736 Entry ID: 68625
Modified: 10/27/2020 @ 0736 Modified ID: 68625

Engine 26 dispatched to 10 Clifford st , apt 301 for smoke detector sounding. Chief 2 responded as well. While on - route, fire alarm updated the call stating they were on the phone with the caller and could hear the detector chirping in the background.

Chief 2 arrived on scene, 3 stroy wood frame building, nothing showing, C2 assumed command.

Engine 26 arrived on scene, made contact and entry to third floor apartment. No detectors sounding, one chirping in the kitchen area. We removed the detector, replaced battery and re installed. The detector would not operate when tested. The detector was then removed from the ceiling and placed on the kitchen table. Faulty detector.

While in the apartment we noted a large presence of bugs on the walls, ceiling and other surfaces.

Chief 2 confirmed to me there is a scheduled walk through of the apartment with codes and the landlord today. They will be addressing the detector issue.

Command terminated, both units in service