



**Biddeford Fire Department  
Incident Report**

**Page: 2  
09/13/2021**

**Incident #: 13-460-IN Exp. 0**

2	Bidd Engine 6 E6	Engine	Disp 02/05/2013 @ 1027 Arr 02/05/2013 @ 1029 Clr 02/05/2013 @ 1124 InQt 02/05/2013 @ 1125 InSv 02/05/2013 @ 1125	3	Suppr	- Investigate - Salvage & overhau
3	Bidd Rescue 8 R008	Medical & rescue uni	Disp 02/05/2013 @ 1027 Arr 02/05/2013 @ 1029 Clr 02/05/2013 @ 1113 InQt 02/05/2013 @ InSv 02/05/2013 @ 1113	2	EMS	- Salvage & overhau
4	Bidd Rescue 10 R010	Medical & rescue uni	Disp 02/05/2013 @ 1028 Arr 02/05/2013 @ 1029 Clr 02/05/2013 @ 1124 InQt 02/05/2013 @ 1125 InSv 02/05/2013 @ 1125	2	EMS	- Salvage & overhau
5	Bidd TOWER 4 T4	Truck or aerial	Disp 02/05/2013 @ 1027 Arr 02/05/2013 @ 1029 Clr 02/05/2013 @ 1125 InQt 02/05/2013 @ 1125 InSv 02/05/2013 @ 1125	1	Suppr	- Salvage & overhau

#	ID	Personnel	Start	End	Dty	Station	App
1	01150	ANTON, PETER	02/05/2013 @ 1027	02/05/2013 @ 1113	DR	CEN	E4
2	04700	Binette, Gerry	02/05/2013 @ 1027	02/05/2013 @ 1125	DR	CEN	E6
3	13000	Cooper, Justin	02/05/2013 @ 1027	02/05/2013 @ 1113	DR	CEN	R008
4	41400	Leach, Matthew	02/05/2013 @ 1028	02/05/2013 @ 1125	DR	CEN	R010
5	10029	MOLINA, BETH	02/05/2013 @ 1028	02/05/2013 @ 1125	T	CEN	R010
6	50780	Morrow, Andrew	02/05/2013 @ 1027	02/05/2013 @ 1125	DR	CEN	T4
7	10028	Ouellette, Derick	02/05/2013 @ 1027	02/05/2013 @ 1113	T	CEN	R008
8	57900	Pothier, John	02/05/2013 @ 1027	02/05/2013 @ 1125	OI	CEN	E6
9	60600	Robinson, Tim	02/05/2013 @ 1027	02/05/2013 @ 1125	ST	CEN	E6
10	64700	SULLIVAN, SHAWN	02/05/2013 @ 1028	02/05/2013 @ 1125	DR	CEN	R010

Incident #: 13-460-IN Exp. 0

NARRATIVE FOR CAPTAIN JOHN POTHIER

Ref: 13-460-IN

Entered: 02/05/2013 @ 1322      Entry ID: 57900  
Modified: 02/05/2013 @ 1322      Modified ID: 57900

Called for alarm activation, reported water problem. Found broken heating pipe in unit 107 causing water damage in this apartment and lower unit L7. Secured water to baseboard in affected unit and secured power to lower unit as water infiltrated electrical fixtures. Set up salvage in both apartments removing water. Management arrived on scene and relieved FD units. Reset Alarm system.