



Biddeford Fire Department
Incident Report

Page: 1
08/17/2021

Incident #: 20-4856-IN Exp. 0

Call #: 20-44980

Location: 10 CLIFFORD ST
10 CLIFFORD ST
BIDDEFORD, ME 04005

Census Tract: 179-
District: Biddeford 09
Station: BIDDEFORD CENTRAL

Officer In Charge: WHEELER, ERIC on 12/10/2020
Report By: WHEELER, ERIC on 12/10/2020
Approved By: WHEELER, ERIC on 12/10/2020

Basic Incident Information

Incident Type: False alarm or false call, other - BFD PULLS/SMOKE
DETECTOR ACTIVATION RESIDENTIAL

Property Use: Multifamily dwelling
Actions Taken: Investigate
Restore fire alarm system

Owner: 10 CLIFFORD ST
10 CLIFFORD ST
BIDDEFORD, ME 04005

Resources Used Summary

Alarm: 12/10/2020 @ 0436 Arrived: 12/10/2020 @ 0442
Cleared: 12/10/2020 @ 0446

Shift: C Alarms: 0 Aid: None

	<u>Apparatus</u>		<u>Personnel</u>
Suppression:	1	Suppression:	3
EMS:	0	EMS:	0
Other:	0	Other:	0

Casualties Summary

	<u>Deaths</u>		<u>Injuries</u>
Fire Service:	0	Fire Service:	0
Civilian:	0	Civilian:	0

People and Entities Involved Type Sex Age Home # Work

1

Biddeford Fire Department
Incident Report

Page: 2
08/17/2021

Incident #: 20-4856-IN Exp. 0

#	Apparatus	Type	Dates/Times	Per Use	Actions Taken
1	Biddeford Engine 24 BIDE24	Engine	Disp 12/10/2020 @ 0437 Arr 12/10/2020 @ 0442 Clr 12/10/2020 @ 0446 InQt 12/10/2020 @ 0446 InSv 12/10/2020 @ 0446	3 Suppr	- Investigate - Restore fire alar

#	ID	Personnel	Start	End	Dty	Station	App
1	20530	Drew, Michael	12/10/2020 @ 0437	12/10/2020 @ 0446	ST	CEN	BIDE24
2	44675	Maloney, Todd	12/10/2020 @ 0437	12/10/2020 @ 0446	DR	CEN	BIDE24
3	68625	WHEELER, ERIC	12/10/2020 @ 0437	12/10/2020 @ 0446	OI	CEN	BIDE24

Incident #: 20-4856-IN Exp. 0

NARRATIVE FOR CAPTAIN ERIC WHEELER

Ref: 20-4856-IN

Entered: 12/10/2020 @ 0510 Entry ID: 68625
Modified: 12/10/2020 @ 0510 Modified ID: 68625

Engine 24 dispatched to 10 Clifford st for smoke detector activation. Fire alarm reports the call came in from a resident on Pike st.

Arrival on scene, three story, wood frame, nothing showing from three sides, D7 with command investigating.

We had just cleared from this scene about an hour earlier for smoke detector activation and found the activated detector head to be on the C side stairs, first floor.

I went straight to C side stairs and found the same first floor detector activated. I removed the detector from power and removed the battery. the remaining detectors silenced.

The occupants of the third floor apartment did evacuate on their own this time.

I explained to the teenage girl we removed one smoke detector and there is no smoke or fire danger, I thanked her for evacuating and told her it is safe to return to their apartment She translated to her mother in their native language.

Command terminated, Engine 24 in service